

45m M/Y Aquarius de Vries

Staircase with a 10 years old varnish which was unregular bleached out with big white patches inside the varnish. Instead of stripping and revarnishing the woodgrain was painted on top of the old varnish. Less time, less dirt and most of all less cost.

